AMSM NOTES

# TH:3- AC MACHINES AND SPECIAL ELECTRICAL MACHINES

Prepared by

ZAHID AKHTAR
GP SAMBALPUR

Comprehensive Academic Notes on AC Machines and Special Electrical Machines

The domain of electrical machinery forms the critical infrastructure of modern industrial energy conversion, enabling everything from large-scale power generation to precision robotics. This exhaustive analysis provides a detailed theoretical, mathematical, and practical exposition of alternating current (AC) machines and special electromechanical energy conversion devices. Following a structured academic syllabus [1], the analysis covers the fundamental principles, operational characteristics, mathematical derivations, numerical applications, and maintenance protocols for three-phase induction motors, single-phase induction motors, synchronous generators (alternators), synchronous motors, and fractional horsepower (FHP) specialized motors.

Unit I: Three-Phase Induction Motors

Working Principle and the Rotating Magnetic Field

The three-phase induction motor operates fundamentally on the principle of electromagnetic induction, functioning without direct electrical connections to the rotor assembly. The foundation of its operation is the rotating magnetic field (RMF). When a balanced three-phase winding, spatially displaced by 120 electrical degrees along the stator periphery, is supplied with balanced three-phase alternating currents that are temporally displaced by 120 degrees, an RMF is established in the air gap.[1] The instantaneous fluxes produced by the individual phases can be expressed mathematically as $\phi_1 = \phi_m \sin(\omega t)$, $\phi_2 = \phi_m \sin(\omega t - 120°)$

, and $\phi_3 = \phi_m \sin(\omega t + 120°)$.[4] By resolving these individual alternating fluxes into horizontal and vertical spatial components at any instant in time, the resultant flux Φ_r is proven to be constant in magnitude and equal to $1.5\phi_m$.[4]

This resultant magnetic field rotates at a constant synchronous speed, denoted as N_s, which is strictly governed by the relationship $N_s = 120f/P$, where f represents the supply frequency in Hertz and P represents the number of magnetic poles for which the stator is wound.[1] As this magnetic field sweeps past the stationary rotor conductors, it induces an electromotive force (EMF) in them according to Faraday's law of electromagnetic induction. Because the rotor circuit is electrically closed, this induced EMF drives circulating currents within the rotor bars. According to Lenz's law, the direction of these induced currents creates a secondary magnetic field that interacts with the stator's RMF to produce an electromagnetic torque, compelling the rotor to rotate in the same direction as the stator field to minimize the relative motion.[7] The rotor can never achieve synchronous speed; if it were to rotate at N_s, the relative motion between the RMF and the rotor conductors would be zero, resulting in zero induced EMF, zero rotor current, and consequently, zero torque.[8] This necessary difference between the synchronous speed (N_s) and the actual mechanical rotor speed (N_r) is termed the slip speed. The fractional slip is defined as $s = (N_s - N_r)/N_s$.[1]

Constructional Details and Rotor Quantities

Three-phase induction motors are classified primarily by their rotor construction: the squirrel cage rotor and the slip ring (or wound) rotor.[1] The squirrel cage rotor consists of a laminated cylindrical core with uninsulated aluminum or copper bars embedded in the peripheral slots. These bars are permanently short-circuited by heavy end rings at both ends, creating a structure resembling a cage. This design is incredibly robust, inexpensive, and requires minimal maintenance, making it the most ubiquitous industrial motor.[11] Conversely, the slip ring induction motor features a three-phase distributed winding on the rotor, identical in pole count to the stator. The terminals of this winding are brought out and connected to three slip rings mounted on the motor shaft. Carbon brushes ride on these slip rings, allowing external variable resistance to be inserted into the rotor circuit. This capability is utilized to limit starting current, drastically increase starting torque, or control the running speed.[1]

Under running conditions, the electrical quantities within the rotor are fundamentally slip-dependent. The frequency of the induced rotor current is directly proportional to the slip, expressed as $f_r = sf$, where f is the stator supply frequency.[13] This phenomenon dictates

that the induced rotor EMF and the rotor leakage reactance also become proportional to slip. If E_2 and X_2 represent the standstill (locked-rotor) induced EMF and reactance per phase respectively, their values under running conditions become $E_{2r} = sE_2$ and $X_{2r} = sX_2$.[14] Consequently, the rotor power factor under running conditions is given by the ratio of rotor resistance to rotor impedance: $\cos \phi_2 = R_2/\sqrt{R_2^2 + (sX_2)^2}$. This mathematical relationship demonstrates that at standstill ($s = 1$), the high rotor reactance results in a poor power factor and low starting torque per ampere. As the motor accelerates and slip decreases, the rotor reactance drops proportionally, leading to an improved rotor power factor in the normal operating range.[14]

Generalized Transformer Concept and Phasor Diagram

The three-phase induction motor is frequently analyzed in academic and industrial literature as a generalized, or rotating, transformer. In a static transformer, alternating electrical energy is transferred from the primary winding to the secondary winding via mutual induction without any physical motion. In an induction motor, the stator acts as the primary winding and the short-circuited rotor acts as the rotating secondary winding.[14] The fundamental difference is that the induction motor converts the transferred electrical energy into mechanical energy. Furthermore, the induction motor features an air gap between the stator and rotor, which introduces a high magnetic reluctance. As a result, an induction motor requires a significantly larger magnetizing current—typically 25% to 40% of the full-load current—to establish the required air-gap flux, compared to the 2% to 5% required by a standard power transformer with a continuous steel core.[18]

To develop the equivalent circuit of an induction motor, the mechanical load on the shaft is modeled as a variable electrical resistance. By dividing the rotor impedance by the slip (s), the total effective rotor resistance becomes R_2/s. This term can be mathematically partitioned into two components: the actual ohmic rotor copper resistance R_2, and a fictitious, slip-dependent load resistance $R_L = R_2(1-s)/s$.[15] This fictitious resistance precisely represents the mechanical power developed by the motor. The phasor diagram of the induction motor under load closely mirrors that of a loaded transformer.[18] The applied stator voltage V_1 opposes the induced stator EMF E_1 and overcomes the stator resistance and leakage reactance voltage drops. The exciting current I_0 comprises the core loss component and the magnetizing component required to drive flux across the air gap. The total primary

stator current I_1 is the complex phasor sum of the no-load current I_0 and the reflected rotor current I_2', which balances the rotor magnetomotive force.[14]

Torque-Slip Characteristics and Numerical Analysis

The electromagnetic torque developed by a three-phase induction motor is a complex function of the slip, applied stator voltage, and internal motor impedances. The generalized expression for torque is derived from the power transferred across the air gap to the rotor, given by the equation $T = \frac{3V^2 R_2/s}{\omega_s}$.[16] Analyzing this fundamental equation reveals three critical operational points on the torque-speed curve: the starting torque (where $s = 1$), the full-load operating torque (where slip is typically 1% to 5%), and the maximum torque, also known as the breakdown or pull-out torque. Through differentiation, the condition for maximum torque occurs when the slip $s_m = R_2/X_2$.[9] At this specific breakdown slip, the maximum torque is mathematically independent of the rotor resistance, although the speed at which this peak torque occurs is directly governed by R_2.[22]

To illustrate these relationships numerically, consider a standard induction motor problem: A 50 Hz, 6-pole three-phase induction motor has a full-load slip of 3% ($s = 0.03$). The rotor resistance R_2 is 0.02Ω per phase, and the standstill rotor reactance X_2 is 0.2Ω per phase.[16] The slip corresponding to maximum torque is calculated as

$$s_m = R_2/X_2 = 0.02/0.2 = 0.1$$

(or 10% slip).[16] The ratio of maximum torque (T_m) to full-load torque (T_{FL}) can be derived using the approximation relation

$$T_m/T_{FL} = (s_m^2 + s^2)/(2ss_m)$$

Substituting the calculated values yields

$$T_m/T_{FL} = (0.1^2 + 0.03^2)/(2 \times 0.03 \times 0.1) = 0.0109/0.006 = 1.82$$ [16]

Furthermore, the ratio of maximum torque to starting torque (T_{st}) is found via the relation

$$T_m/T_{st} = (s_m^2 + 1)/(2s_m)$$

This evaluates to

$$(0.1^2 + 1)/(2 \times 0.1) = 1.01/0.2 = 5.05$$ [16] These numerical calculations demonstrate the robust overload capacity of the motor, capable of handling 82% more torque than full load before stalling. However, it also highlights a relatively modest starting torque profile (only about 36% of maximum torque, or roughly 65% of full-load torque), which is highly typical of standard low-resistance squirrel cage rotor designs.

Four-Quadrant Operation and Drive Control

Fig. 2.3 Four quadrant operation of a motor driving a hoist load

In sophisticated industrial applications, such as heavy-duty hoists, cranes, and electric traction drives, induction motors must operate seamlessly across all four quadrants of the speed-torque plane. In Quadrant I (Forward Motoring), both the rotational speed and the developed torque are positive. The machine converts electrical power from the grid into mechanical power to accelerate or drive a load upward.[23] In Quadrant II (Forward Braking or Regeneration), the speed remains positive, but the electromagnetic torque becomes negative, opposing the motion. Here, the motor acts as an induction generator, absorbing kinetic energy from the mechanical load and returning it to the electrical supply as active power.[24] This regenerative braking occurs naturally when the rotor is driven above synchronous speed by an overhauling load (like a descending elevator counterweight) or artificially through flux-weakening and frequency reduction in modern inverter drives.[26] In Quadrant III (Reverse Motoring), both torque and speed are negative, utilizing grid power to drive the load in the opposite direction.[23] In Quadrant IV (Reverse Braking or Plugging), the speed is negative but the torque is positive, actively decelerating a reverse-moving load.[24] Plugging is a particularly severe form of braking achieved by reversing the phase sequence of the stator supply (swapping two input lines). This abruptly reverses the direction of the rotating magnetic field while the rotor is still spinning in the original direction, inducing a massive slip ($s > 1$) and generating violent braking torque accompanied by extremely high rotor copper losses that

dissipate as heat.[29]

Modern variable speed drives execute this four-quadrant control precisely. Variable Voltage Variable Frequency (VVVF) drives manipulate the input frequency to dictate the synchronous speed while simultaneously adjusting the applied voltage to maintain a constant Volts-per-Hertz (V/f) ratio. This constant ratio ensures that the internal air-gap flux remains constant at its optimal designed value, thereby preventing magnetic core saturation and allowing the induction motor to deliver rated torque smoothly across a broad speed range from zero to base speed.[8]

Starting Method	Mechanism	Application & Characteristics
Direct-On-Line (DOL)	Connects motor directly to full line voltage.	Very high starting current (5-8x full load); suitable only for small motors due to severe grid voltage dips.
Star-Delta Starter	Starts motor in Star (reduces phase voltage by $\sqrt{3}$), then switches to Delta.	Reduces starting current and torque to 1/3 of DOL values; highly common for medium-sized industrial motors.
Auto-Transformer	Uses tapped transformers to apply a fraction of line voltage during start.	Adjustable starting voltage and torque; expensive but provides excellent torque-to-current starting ratios.
Rotor Resistance	Inserts external resistors via slip rings into the rotor circuit.	Applicable *only* to slip-ring motors; provides maximum starting torque with minimum starting current.
Soft Starter	Uses thyristors to smoothly	Eliminates mechanical

	ramp up the RMS voltage applied to the stator.	shock and current spikes; seamlessly integrates into modern automated control systems.
Table 1: Comparison of Starting Methods for Three-Phase Induction Motors.[1]		

Maintenance Protocols for Induction Motors

The operational longevity of three-phase induction motors relies on rigorous predictive and preventative maintenance protocols. Routine visual and mechanical inspections must continuously assess the structural frame, cooling fins, and fan cowls for dust or debris accumulation that severely impedes thermal dissipation.[32] Electrical testing includes winding continuity checks and high-voltage insulation resistance testing using a megohmmeter (Megger) to detect degrading insulation and potential ground faults.[33] Bearing failure remains the dominant cause of induction motor breakdown. Lubrication schedules must be strictly adhered to; however, over-lubrication is a frequent and destructive error that elevates bearing temperatures and physically forces grease past seals into the stator windings, chemically degrading the insulation.[33] Furthermore, predictive maintenance increasingly deploys thermal imaging cameras during operation to identify localized hot spots in terminal boxes, bearings, and stator enclosures, enabling the early detection of high-resistance electrical connections or mechanical binding before catastrophic failure occurs.[35]

Unit II: Single-Phase Induction Motors

Double-Field Revolving Theory and Starting Mechanisms

Unlike polyphase motors, a single-phase induction motor subjected to a single-phase alternating current produces a pulsating magnetic field rather than a rotating one. Consequently, it possesses zero inherent starting torque and is not self-starting.[36] This phenomenon is mathematically and physically explained by Ferrari's Double-Field Revolving Theory, which postulates that any alternating uniaxial physical quantity can be mathematically resolved into two oppositely rotating vectors, each of half the original magnitude.[37] Thus, an alternating sinusoidal stator flux $\Phi_m \sin(\omega t)$ is composed of a forward rotating magnetic field and a backward rotating magnetic field. Both fields possess a magnitude of $\frac{1}{2}\Phi_m$ and

rotate at the synchronous speed ω_s, but in opposite directions.[36] At standstill, these two counter-rotating fields induce equal and opposite electromagnetic torques in the rotor cage, resulting in a net torque of absolute zero.[37] However, if the rotor is mechanically accelerated in either direction by an external force, the relative slip with respect to the forward field (s) decreases, while the slip relative to the backward field ($2 - s$) increases. This imbalance produces a strong net forward torque that sustains continuous rotation.[36]

To render the machine self-starting from rest, an artificial phase shift must be introduced to simulate a true two-phase rotating field. This is almost universally achieved by incorporating an auxiliary (starter) winding positioned physically 90 electrical degrees apart from the main stator winding.[40]

Motor Variations and Torque-Speed Characteristics

Single-phase induction motors are categorized based on their specific starting methodology, auxiliary circuit components, and constructional nuances [1]:

Resistance Start (Split-Phase) Motors: By designing the auxiliary winding with a high resistance-to-reactance ratio compared to the main winding, a temporal phase difference is created between the two winding currents. This generates a weak but sufficient rotating magnetic field to initiate rotation. A centrifugal switch disconnects the auxiliary circuit once the motor reaches approximately 75% of synchronous speed to prevent the fine wire of the

Split Phase Motor

Main winding

I_m

Rotor

I_S

1-phase supply

V

Starting Winding

S

Centrifugal switch

uxiliary winding from overheating.[38]

Capacitor Start Motors: By placing a highly capacitive electrolytic capacitor in series with the auxiliary winding, the phase angle between the main and auxiliary currents approaches an ideal 90 degrees. This yields an exceptionally high starting torque, making these motors ideal for heavy-duty applications like compressors and large pumps.[38] Similar to split-phase motors, a centrifugal switch removes the capacitor and auxiliary winding from the circuit as the motor


nears operating speed.[41]

Capacitor Start, Capacitor Run Motors: This premium variant utilizes two capacitors. A high-value starting capacitor provides the initial breakaway torque and is subsequently switched out, while a lower-value, continuous-duty run capacitor remains permanently in series with the auxiliary winding. This design not only provides excellent starting torque but also drastically improves the running power factor, efficiency, and smoothness of the motor under load.[40]

Shaded Pole Motors: This is a highly simplified, rugged, and inexpensive motor that features salient stator poles, where a small portion of each pole face is encircled by a short-circuited copper band known as a shading coil.[1] The alternating main flux induces a massive current in the shading coil, which in turn produces a counter-flux that opposes changes in the main flux. This physical interaction causes the magnetic flux in the shaded portion of the pole to lag significantly behind the flux in the unshaded portion, creating a sweeping magnetic field across the pole face that drags the rotor along.[42] Because the $I^2 R$ power loss in the shading coil is continuous, these motors possess very low starting torque and abysmal efficiency (often below 20%), restricting their use strictly to sub-fractional horsepower applications such as small exhaust fans, record players, and timing devices.[38]

Repulsion Type Motors: These motors feature a stator similar to a single-phase induction motor but possess a wound rotor connected to a commutator, similar to a DC armature. The brushes riding on the commutator are short-circuited together rather than connected to a supply. By physically shifting the brush axis away from the stator magnetic axis, heavy currents are induced in the rotor by transformer action, producing massive starting torque (up to 3 times full-load torque) with relatively low starting current.[44] Their use has declined due to the high maintenance requirements of the commutator and brushes.

AC Supply

N

Rotor

Brushe

Magnetic Poles

Com

S

D

©Elprocus.com

Series and Universal Motors: A series motor features the field and armature windings connected in series. When designed with fully laminated magnetic cores to minimize severe AC eddy current losses, it can operate on both AC and DC power supplies, earning the name "Universal Motor".[11] These motors are unique in that they do not operate at synchronous speed; instead, they operate at extremely high speeds (often exceeding 10,000 RPM) that are highly sensitive to the applied load. This high power-to-weight ratio makes them the standard choice for portable power tools, vacuum cleaners, and kitchen blenders.

Hysteresis Motors: The hysteresis motor utilizes a perfectly smooth, solid steel cylindrical rotor with exceptionally high magnetic retentivity, lacking any localized windings, slots, or squirrel cage.[45] When subjected to the stator's rotating magnetic field, eddy currents and magnetic hysteresis effects induce torque. The defining operational characteristic of this specialized motor is that the torque generated by magnetic hysteresis remains strictly constant from standstill all the way up to synchronous speed.[45] Because it accelerates to synchronism seamlessly and lacks rotor slots that cause magnetic pulsation and aerodynamic noise, it operates with absolute acoustic quietness, making it indispensable for precision timing devices, clocks, and high-fidelity audio turntables.[46] The hysteresis torque equation is proportional to the hysteresis loss, denoted as $P_h = k_h f_1 B^{1.6}$, demonstrating the motor's heavy reliance on the intrinsic metallurgical properties of the rotor material.[45]

Maintenance of single-phase motors generally mirrors that of three-phase machines, with the critical addition of servicing the specific starting mechanisms. Centrifugal switches must be periodically cleaned of dust and inspected for pitted contacts, as a failed switch will either prevent starting or leave the start winding engaged, leading to rapid thermal destruction.[41] Capacitors must be visually inspected for bulging or leaking electrolyte and tested with a

capacitance meter.[51]

Unit III: Three-Phase Alternators

Constructional Topology and Armature Windings

Three-phase alternators, or synchronous generators, operate on the fundamental principles of Faraday's laws of electromagnetic induction but physically invert the arrangement typically seen in DC machines. Alternators feature a stationary armature winding (the stator) and a rotating magnetic field (the rotor).[52] This stationary armature design is absolutely critical for modern high-voltage machines. It eliminates the need to extract thousands of amperes at extreme voltages through moving slip rings and brushes, allowing for vastly superior dielectric insulation and the robust mechanical bracing required to withstand immense electromagnetic forces during short circuits.[52] Rotors are divided into two distinct categories: salient-pole designs (featuring projecting poles, large diameters, and short axial lengths, used for low-speed hydroelectric generation) and cylindrical or non-salient designs (smooth rotors with long axial lengths, used for high-speed steam turbine applications).[1]

Armature windings are systematically placed in the stator slots and can be configured as either single-layer or double-layer arrangements.

Synchronous Generator Construction

Feature	Single-Layer Winding	Double-Layer Winding
Coil Placement	One coil side per slot	Two coil sides per slot (top and bottom)
Inter-layer Insulation	Not required	Strictly required to separate phases
Coil Pitching	Restricted entirely to full-pitch configurations	Allows fractional-pitch (short-pitch) coils
Efficiency & Waveform	Lower efficiency, higher	Higher efficiency, improved

	harmonic distortion	sinusoidal waveform
Aesthetics/Neatness	Messier end-winding overhangs	Neat, uniform, and compact end-winding geometry
Table 2: Technical Comparison of Single-Layer and Double-Layer Alternator Windings.[55]		

Double-layer windings are universally preferred in modern commercial alternators as they uniquely facilitate short-pitching (also known as chording).[56] Short-pitching deliberately spans the coil less than a full 180 electrical degrees. This geometrical arrangement acts as a spatial filter to eliminate specific spatial harmonics (such as the 5th and 7th harmonics) from the air-gap flux, resulting in a purer sinusoidal output voltage. Furthermore, it saves significant expensive copper material in the inactive end-turns of the machine.[59]

EMF Equation and Numerical Application

The magnitude of the generated EMF per phase in an alternator is dependent on the rotational frequency, the magnetic flux per pole, and the specific winding geometry. The fundamental RMS voltage equation is formulated as $E_{ph} = 4.44 f \Phi T_{ph} K_p K_d$.[60] Here, K_p represents the pitch factor, defined as the ratio of the phasor sum of induced EMFs in a short-pitched coil to the arithmetic sum of EMFs in a full-pitched coil. It is calculated as $K_p = \cos(\alpha/2)$, where α is the chording angle in electrical degrees. The distribution factor, K_d, accounts for the fact that the coils comprising a single phase are distributed across multiple slots rather than concentrated in one massive slot. This distribution causes the individual coil EMFs to be slightly out of phase with one another. It is expressed as $K_d = \frac{\sin(m\beta/2)}{m \sin(\beta/2)}$, where m is the number of slots per pole per phase and β is the angular displacement between adjacent slots.[59]

Consider a comprehensive numerical problem detailing a 16-pole, 3-phase star-connected alternator running at 375 rpm, featuring 144 slots with 6 conductors per slot. The main flux per pole is 0.03 Wb, and the coil span is explicitly short-pitched to 160 electrical degrees.[60] First, the electrical frequency is calculated: $f = PN/120 = (16 \times 375)/120 = 50$ Hz.[60]

Next, determine the pitch factor (K_p). Since a full pitch is defined as $180°$ and the actual coil

span is $160°$, the short-pitch chording angle $\alpha = 20°$. Thus,

$$K_p = \cos(20°/2) = \cos(10°) = 0.985$$ [60] To find the distribution factor (K_d), calculate

the slots per pole per phase: $m = 144/(16 \times 3) = 3$. The slot angle

$$\beta = 180°/(144/16) = 20°$$ electrical. Therefore,

$$K_d = \sin(3 \times 20°/2)/[3\sin(20°/2)] = \sin(30°)/[3\sin(10°)] = 0.96$$ [60] The total

turns per phase T_{ph} must be deduced. Total conductors in the machine

$$Z = 144 \text{ slots} \times 6 \text{ conductors/slot} = 864.$$ Conductors per phase $= 864/3 = 288$.

Since two conductors make one turn, turns per phase $T_{ph} = 288/2 = 144$. [60] Finally, the induced EMF per phase is computed as

$$E_{ph} = 4.44 \times 50 \times 0.03 \times 144 \times 0.985 \times 0.96 = 906.87$$ Volts. [60]

Armature Reaction and Voltage Regulation

When an alternator is connected to a load, the resulting armature current produces its own distinct magnetic field, which fundamentally interacts with and distorts the main rotor field. This complex electromagnetic phenomenon, known as armature reaction, profoundly impacts the generated terminal voltage depending entirely on the load's power factor. At unity power factor (purely resistive load), the armature flux is primarily cross-magnetizing, distorting the main field without heavily reducing its average magnitude. At a zero power factor lagging load (purely inductive), the armature flux directly opposes the main rotor flux, causing severe demagnetization and a sharp, detrimental drop in terminal voltage. Conversely, at a zero power factor leading load (purely capacitive), the armature flux actively aids the main flux, creating a magnetizing effect that artificially raises the terminal voltage beyond the no-load value. [54]

Voltage regulation is a critical performance metric defined as the percentage increase in terminal voltage when the full load is completely removed, while keeping the prime mover speed and DC field excitation strictly constant. It is expressed as:

$$\%\text{Regulation} = \frac{E_0 - V}{V} \times 100$$ [59] Because testing massive utility-scale alternators under physical full load is economically and practically impossible, regulation is predetermined via several indirect analytical methods. [59]

Regulation Method	Technical Description	Accuracy Profile

Direct Loading	Physically loading the machine to rated capacity.	100% accurate, but strictly limited to fractional horsepower laboratory machines.
EMF Method (Synchronous Impedance)	Combines armature reaction and leakage reactance into a single fictitious "synchronous impedance".	Highly pessimistic; yields regulation values significantly higher than reality due to assuming an unsaturated magnetic core.
MMF Method (Ampere-Turn)	Replaces leakage reactance voltage drops with fictitious armature reaction MMFs.	Optimistic; yields regulation values slightly lower than actual physical performance.
ZPF Method (Potier Triangle)	Separates leakage reactance and true armature reaction using open-circuit and zero-power-factor test data.	Highly accurate; accounts for magnetic saturation and isolates distinct internal voltage drops.
Table 3: Comparison of Voltage Regulation Predetermination Methods.[54]		

The Potier Triangle (ZPF) Method: This advanced technique accurately separates the distinct effects of armature leakage reactance and armature reaction MMF, providing a highly precise regulation value. It relies on the assumption that the open-circuit characteristic (OCC) relates MMF and voltage accurately under loaded conditions and that leakage reactance remains independent of field excitation.[54] The procedure involves plotting the OCC and the zero-power-factor (ZPF) characteristic curve. By geometrically translating a Potier triangle between these curves, the vertical leg of the triangle yields the exact leakage reactance voltage drop ($I_a X_{aL}$), and the horizontal leg isolates the armature reaction MMF (F_{aR}). With these parameters independently isolated, the true generated internal EMF (E_g) and subsequently the required no-load field excitation can be deduced, providing a highly accurate

predetermination of the alternator's voltage drop.[54]

Two-Reaction Theory for Salient Poles: Blondel's Two-Reaction Theory was developed to address the magnetic non-uniformity inherent in salient-pole rotors, where the air gap varies circumferentially, making standard synchronous impedance calculations wildly inaccurate.[59] The theory resolves the total armature MMF into two mutually perpendicular axes: the direct axis (d-axis) aligned directly with the salient pole center, representing the path of minimum magnetic reluctance, and the quadrature axis (q-axis) aligned with the interpolar gap, representing the path of maximum magnetic reluctance.[54] The stator current I_a is divided into I_d and I_q. Because the reluctances differ, the machine exhibits two distinct reactances, denoted as X_d and X_q, where $X_d > X_q$. The total excitation voltage equation becomes a complex phasor summation: $E_f = V + I_a R_a + j I_d X_d + j I_q X_q$, providing a precise mathematical model of salient machine behavior under heavy load.[54]

Unit IV: Synchronous Motors

Working Principle and Power Angle

The synchronous motor is structurally identical to the three-phase alternator. It operates through the continuous magnetic interlocking of the rotating stator field and the constant DC magnetic field of the rotor.[68] When the stator is supplied with three-phase AC power, it generates a synchronously revolving magnetic field. The rotor, excited by a separate DC source via slip rings, creates distinct, unchanging North and South poles. As the rotor accelerates near synchronous speed via auxiliary starting methods, the opposing magnetic poles of the stator and rotor fields attract and magnetically interlock. From this moment onward, the motor strictly operates at exactly synchronous speed, irrespective of the applied load.[59]

If mechanical load is applied to the output shaft, the rotor does not slow down; instead, the physical rotor poles fall slightly behind the imaginary rotating stator poles by a physical angle δ, known as the load angle, power angle, or torque angle.[54] This angular displacement is the fundamental mechanism that allows the motor to draw more active power from the supply to meet the mechanical demand. The real power developed per phase for a salient pole synchronous motor is derived from the complex power input and is expressed exactly as:

$$P_{1\phi} = \frac{V E_f}{X_d} \sin\delta + \frac{V^2}{2}\left(\frac{1}{X_q} - \frac{1}{X_d}\right) \sin 2\delta$$ [54] The first term in this equation represents the excitation power, which relies entirely on the applied DC field. The second term represents the

reluctance power, which stems entirely from the uneven air gap (saliency) of the rotor and exists even if the DC field excitation fails.[54]

Effect of Excitation at Constant Load and V-Curves

A unique and highly valuable characteristic of the synchronous motor is its ability to operate at varying power factors solely by altering its internal DC field excitation. When operating under a constant mechanical shaft load, a change in field excitation directly alters the magnitude of the induced back EMF (E_b) and forces a phase shift in the alternating current drawn from the grid.[59]

Consider a practical numerical application demonstrating this phenomenon: A synchronous motor operates from a $V = 6351$ V per phase grid, drawing 100 A at 0.8 lagging power factor to drive a constant load. The machine has a synchronous reactance $X_s = 30\Omega$ and negligible armature resistance. The internal reactive voltage drop is $E_r = I \times X_s = 3000$ V. The back EMF required for an under-excited (lagging) condition is calculated via the geometric cosine rule: $E_b = \sqrt{V^2 + E_r^2 - 2VE_r \cos(\theta - \phi)}$, where θ is the impedance angle and ϕ is the power factor angle. This yields a required internal voltage of $E_b = 5066$ V.[59] Conversely, if the plant operator increases the DC field current to make the motor over-excited, targeting a leading power factor of 0.8 to correct the plant's overall power factor, the mathematical reality shifts to $E_b = \sqrt{V^2 + E_r^2 - 2VE_r \cos(\theta + \phi)}$, demanding an internal voltage of $E_b = 8449.26$ V.[59] This mathematical reality proves that low internal EMF corresponds to drawing lagging reactive current, whereas a high internal EMF causes the motor to actively supply reactive power (leading current) back to the grid.

Plotting the scalar magnitude of the armature current against the DC field current for a constant active load yields the characteristic **V-curve**.[71] The lowest geometric point of the V-curve corresponds precisely to unity power factor, where the armature current is at its absolute minimum required to sustain the mechanical load.[70] Decreasing the field current moves the operation up the left side of the curve (lagging PF, under-excited), while increasing it moves up the right side (leading PF, over-excited). Inversely, plotting the power factor against the field current yields the **Inverted V-curve**, mapping out a peak at unity power factor.[31] Because of this unique capability, large, unloaded, heavily over-excited synchronous motors are frequently installed at industrial substations specifically to act as "synchronous condensers," dynamically correcting the poor, lagging power factors created by massive banks of induction motors.[68]

Hunting and Oscillatory Stability

Synchronous motors are inherently susceptible to a dynamic instability known as "hunting" or phase swinging.[1] When the mechanical load on the shaft changes abruptly, the rotor must physically shift to a new load angle δ to balance the newly demanded electromagnetic torque. However, due to the massive rotational mechanical inertia of the rotor assembly, it overshoots the required equilibrium position. This triggers a restoring synchronizing torque that pulls it back, causing the load angle to oscillate rhythmically around its final steady-state value in a spring-mass-like mechanical resonance.[73] This oscillation induces dangerous cyclic mechanical stress on the shaft, causes violent power swings in the supply grid, and, if the oscillation frequency matches the natural mechanical resonant frequency of the system, can cause the motor to lose magnetic synchronism entirely and violently stall.[74]

To actively suppress hunting, synchronous machines are universally fitted with damper (amortisseur) windings. These consist of heavy copper or brass bars embedded deeply into the pole faces of the rotor and short-circuited by end rings, essentially forming a partial squirrel cage.[73] During normal, steady-state synchronous operation, these bars rotate at the exact same speed as the stator RMF; they cut no magnetic flux, and no current is induced in them. However, during an episode of hunting, the relative motion between the oscillating rotor and the synchronously rotating stator field induces massive, localized short-circuit currents in the damper bars. According to Lenz's law, the resulting induction torque acts strictly to oppose the relative oscillatory motion, rapidly damping the phase swing by extracting the kinetic energy of the oscillation and dissipating it as heat, thereby stabilizing the rotor.[73] Furthermore, this induction action provides the critical starting torque required to accelerate the motor near synchronous speed before the DC field is switched on, elegantly resolving the motor's inherent inability to self-start from rest.[59]

Efficiency and Losses

The overall efficiency of synchronous motors is governed by the rigorous thermodynamic management of operational losses. Electrical (copper) losses, quantified as I^2R, manifest as heat in both the AC stator windings and the DC rotor field windings.[77] Magnetic (core) losses occur primarily in the stator iron due to the alternating flux and include hysteresis losses (dependent on the metallurgical retentivity of the steel) and eddy current losses (minimized by using ultra-thin silicon steel laminations).[78] Mechanical losses encompass bearing friction and aerodynamic windage resistance, which is particularly severe in salient-pole rotors due to the fan-like churning of air by the projecting poles.[78] Modern Permanent Magnet Synchronous Motor (PMSM) variants entirely eliminate rotor copper losses because the permanent magnets provide the requisite field flux without drawing excitation current, yielding system efficiencies

frequently exceeding 95%.[77]

Unit V: Fractional Horse Power (FHP) and Special Motors

Reluctance Motors: Synchronous vs. Switched

Reluctance motors operate on the fundamental physical principle that magnetic flux will always seek the path of least magnetic reluctance. The rotor experiences a reluctance torque that forces it to align its salient poles with the energized stator poles to minimize the reluctance of the air gap.[82]

Synchronous Reluctance Motors (SynRM): This modern machine pairs a standard, distributed-winding AC induction motor stator with a highly specialized rotor entirely devoid of permanent magnets or copper windings. The rotor utilizes complex axial or radial steel laminations embedded with strategic air barriers (flux slits) to create distinct paths of high and low magnetic reluctance (defining the d-axis and q-axis).[82] Because there is no rotor cage or field winding, rotor I^2R copper losses are virtually zero, allowing SynRMs to achieve operational efficiencies far superior to premium induction motors while running much cooler.[84] They run purely at synchronous speed and require highly sophisticated variable frequency drives utilizing vector control algorithms to constantly monitor the torque angle and manage inherent torque ripple.[84]

Switched Reluctance Motors (SRM): Unlike the SynRM, the SRM features a doubly salient construction, meaning both the stator and the rotor have highly distinct, projecting iron poles.[82] The stator poles hold simple, concentrated windings, while the rotor is merely a shaped block of laminated iron with no active components. Electromagnetic torque is produced by sequentially pulsing discrete blocks of direct current through diametrically opposite stator coils, forcefully pulling the nearest rotor poles into alignment one by one.[82] Because the electrical phases must be switched at highly specific rotor angles to maintain continuous forward rotation, SRMs cannot operate directly from a grid; they depend completely on closed-loop drive electronics utilizing high-resolution optical encoders or Hall-effect position sensors.[82] While structurally indestructible and capable of speeds exceeding 30,000 RPM, SRMs suffer from severe acoustic noise and vibration due to the violent radial magnetic forces generated during the pulsed phase switching.[82]

| Feature	Synchronous Reluctance Motor (SynRM)	Switched Reluctance Motor (SRM)
Stator Construction	Conventional distributed multiphase AC winding	Concentrated winding coils on salient poles
Rotor Construction	Round rotor with internal air flux barriers	Salient pole structure (doubly salient geometry)
Current Profile	Continuous, smooth sinusoidal AC currents	Discontinuous, pulsed DC current blocks
Acoustic Noise	Quiet operation, acoustically similar to induction motors	Extremely noisy due to impulsive radial magnetic forces
Control Method	Field Oriented Control (Continuous Vector Drive)	Position-dependent discrete sequential phase switching
Table 4: Operational and Constructional Distinctions		

between SynRM and SRM.[82]		

Permanent Magnet Motors (PMSM and BLDC)

Both Permanent Magnet Synchronous Motors (PMSM) and Brushless DC (BLDC) motors substitute traditional, loss-inducing electromagnetic field coils on the rotor with high-coercivity rare-earth permanent magnets (typically Neodymium-Iron-Boron).[80] This substitution absolutely abolishes rotor excitation losses, vastly improving the power-to-weight ratio, volumetric torque density, and dynamic thermal response of the machine.[80]

While physically similar from an external perspective, they differ profoundly in their internal stator winding distribution and required control architecture. The PMSM features sinusoidally distributed stator windings carefully designed to generate a smooth, purely sinusoidal back EMF.[90] Control relies on complex Field Oriented Control (FOC) mathematical algorithms that constantly map the rotor position via high-resolution optical encoders. The drive uses this data to maintain the stator MMF vector at precisely 90 electrical degrees relative to the permanent magnet flux axis under all load conditions, ensuring maximum torque output and minimizing mechanical ripple.[84]

In stark contrast, the BLDC motor features concentrated stator windings that produce a trapezoidal back EMF profile.[80] Its operation effectively mirrors an inverted standard DC motor, where the mechanical brush-and-commutator assembly is replaced entirely by a digital electronic commutator (a three-phase inverter).[80] Using simple, low-cost Hall-effect sensors to detect the rotor's magnetic poles, the drive energizes the stator coils in a discrete 6-step sequence, reacting instantaneously to position feedback. The complete elimination of physical carbon brushes eradicates sparking, mechanical friction, and the need for frequent maintenance, rendering the BLDC motor intrinsically safe for hazardous explosive environments and highly suitable for high-speed aerospace, medical, and robotic applications.[80]

Stepper Motors and Servomotors

Stepper Motors: Unlike continuous rotation machines, stepper motors translate discrete digital electrical pulse inputs into precise, definite angular mechanical movements (steps).[82] They are constructed in three primary topologies: Variable Reluctance (using a soft iron multiphase toothed rotor that seeks minimum reluctance paths), Permanent Magnet (utilizing a radially magnetized cylindrical rotor), or Hybrid types (combining PM stators with highly toothed rotors to achieve exceptional holding torque and micro-stepping angular resolution).[82] Because a specific sequence of electronic pulses dictates an exact angular displacement, stepper motors can execute highly precise positional control in an entirely open-loop architecture—requiring no feedback encoder to verify position, provided the motor does not mechanically stall.[82] This deterministic behavior makes them ubiquitous in computer peripherals, 3D printers, CNC machinery, and textile manufacturing robotics.[82]

Servomotors: Servomotors are not a specific class of electromagnetic machine, but rather motors purposefully engineered and integrated into high-performance closed-loop motion control systems requiring exceptional dynamic response, rapid acceleration, and precise holding torque.[82] DC Servomotors typically utilize separate field excitation or permanent magnets, creating a highly linear torque-speed curve with a steep negative slope. This inherent negative slope acts as viscous mechanical damping, naturally preventing positional overshoot during rapid point-to-point movements.[82] AC Servomotors are typically modified two-phase induction motors or PMSMs driven by advanced PWM controllers. They often utilize a

specialized "drag-cup" rotor construction characterized by extremely thin, low-mass conductive aluminum or copper cylinders.[97] This exceptionally low mechanical rotational inertia allows the motor shaft to accelerate, decelerate, and reverse direction virtually instantaneously, perfectly matching the high-frequency command signals processed from an

integral position encoder or resolver.[96]

Specification	AC Servomotor	DC Servomotor
Feedback Mechanism	High-resolution optical encoders or resolvers	Optical encoders or analog potentiometers
Torque Profile	Constant torque available across variable speeds	High starting torque, but severely declines at high speed
Inertia & Response	Very low inertia (drag-cup design), ultra-rapid response	Higher inertia due to heavy iron armature core
Maintenance	Minimal (no commutators/brushes to wear out)	High (carbon brush and copper commutator wear)
Table 5: Technical Comparison of AC and DC		

Servomotors for Closed-Loop Control Systems.[82]		

Through mastering the fundamental mathematical electromagnetics—such as the double-field revolving theory, the intricacies of synchronous impedance regulation, and the contemporary realities of digital PWM drive integration—modern engineering continues to push the boundaries of efficiency and precision in electromechanical energy conversion.